

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	0	(milling adj head and clamping adj element and recess and cutting adj insert and inclination and adjusting and wedge).clm.	US-PGPUB	2005/10/12 12:44
2	BRS	L2	0	(milling adj head and clamping adj element and recess and cutting adj insert and inclination and adjusting).clm.	US-PGPUB	2005/10/12 12:40
3	BRS	L3	0	(milling adj head and clamping adj element and recess and cutting adj insert and inclination and adjust\$).clm.	US-PGPUB	2005/10/12 12:40
4	BRS	L4	0	(milling adj head and clamping adj element and recess and cutting adj insert).clm.	US-PGPUB	2005/10/12 12:41
5	BRS	L5	2	(milling adj head and cutting adj insert).clm.	US-PGPUB	2005/10/12 12:41
6	BRS	L6	0	(milling adj head and clamping adj element and recess).clm.	US-PGPUB	2005/10/12 12:41
7	BRS	L7	0	(milling adj head and clamping adj element).clm.	US-PGPUB	2005/10/12 12:42
8	IS&R	L8	2286	(407/35-41,43-46,118,119).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/10/12 12:43
9	BRS	L9	430	8 and clamping	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/10/12 12:43
10	BRS	L10	0	(milling adj head and clamping adj element and recess and cutting adj insert and inclination and adjusting and wedge)	US-PGPUB	2005/10/12 12:44
11	BRS	L11	0	milling adj head and clamping adj element and recess and cutting adj insert	US-PGPUB	2005/10/12 12:44
12	BRS	L12	1	milling adj head and clamping adj element and recess	US-PGPUB	2005/10/12 12:44
13	BRS	L13	178	milling adj head	US-PGPUB	2005/10/12 12:44
14	BRS	L14	2	8 and 13	US-PGPUB	2005/10/12 12:45